

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated:

It is certified that an inspection team headed by AEE, RWSS sub div- No- 1

(Name of Officers with designation) from RWS&S Division, Bargarh

(Name of Department/ Office) inspected the **BETHANY CONVENT SCHOOL, NAGENPALI ROAD, TORA,**

**BARGARH** on dated 3/7/2023 (date of inspection), checked the water test report submitted

by the school and found that the school has potable drinking water for students and staff of the institution

and is having provision for running water in the toilets and maintaining hygienic sanitation condition in the

school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt. The above is valid

for a period of 9/7/2024

Signature with Seal:  3/7/23

Name : .....

Designation : Executive Engineer

Assistant Engineer of the Govt. Public Health Department  
(PHED)/ Authorised officer of the Local Body

Name & Address of the Office / Department :

RWS&S Division, Bargarh, Near Civil ITI  
Bargarh

To,

**BETHANY CONVENT SCHOOL**

**NAGENPALI ROAD**

**TORA, BARGARH (ODISHA)**

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

## DISTRICT LEVEL LABORATORY, RWS&S DIVISION, BARGARH

The water quality report of one no of water sample collected & submitted by the Principal, Bethany Convent School ,Orissa, Bargarh is mentioned below.

Testing Date: - ~~01.07~~ 2023

| Sl<br>No | Chloride<br>in<br>mg/ltr               | Hardness<br>in mg/ltr              | Iron<br>in<br>mg/ltr               | Fluoride<br>in<br>mg/ltr           | PH<br>in<br>range | TDS<br>in<br>mg/ltr                    | Alkalinity<br>in<br>mg/ltr         | Turbidity<br>in<br>NTU        | Bacteria<br>Total<br>Coliform     | Bacteria<br>E-Coli                |
|----------|--|------------------------------------|------------------------------------|------------------------------------|-------------------|--|------------------------------------|-------------------------------|-----------------------------------|-----------------------------------|
|          | Permissible<br>limit<br>1000<br>mg/ltr | Permissible<br>limit<br>600 mg/ltr | Permissible<br>limit<br>1.0 mg/ltr | Permissible<br>limit<br>1.5 mg/ltr | 6.5 -<br>8.5      | Permissible<br>limit<br>2000<br>mg/ltr | Permissible<br>limit<br>600 mg/ltr | Permissible<br>limit<br>5 NTU | Permissible<br>limit<br>00 Number | Permissible<br>limit<br>00 Number |
| 1        | 76 mg/ltr                              | 140 mg/ltr                         | 0.08 mg/ltr                        | 0.35 mg/ltr                        | 6.69              | 364 mg/ltr                             | 80 mg/ltr                          | 1.5                           | 00                                | 00                                |

  
Jr. Lab Assistant  
RWS&S Division, Bargarh



Email-eerwss bgh@nic.in

**Office of the Executive Engineer, RWS&S Division, Bargarh.**

No. 2635 / Dated the 03.07.2023 /

To,

**The Principal  
Bethany Convent School  
Bargarh ,Orissa**

Sub :- Water Quality Report

Ref:- Your letter no BCS/312/2023-24 / Dated 20.06.2023

Sir,

With reference to the subject cited above, the water quality report of one no of water sample collected & submitted by **the Principal, Bethany Convent School ,Orissa, Bargarh** is enclosed herewith for information and necessary action .

Encl :- As above

Yours faithfully

  
**Executive Engineer  
RWS&S Division, Bargarh**